

CASE STUDY

Toilet Water Feed Line Ruptured

LOCATION

Cayman Island luxury condominium building with 40 suites.

PROBLEM IDENTIFIED

A toilet water feed line ruptured while a suite was vacant. The damage caused \$250,000 in water damage, including damage to three suites located on the floor below.

SOLUTION

RSC-900-AW were installed into each suite. Each system has multiple sensors at leak points.

The system has caught many leaks since its installation four years ago.

