

# CASE STUDY

## Protecting Older Building from Wasted Water Use

### LOCATION

A sixty-unit luxury condominium building in South Florida.

### PROBLEM IDENTIFIED

The older building was having problems with wasted water use and water damage, which caused leaks in the suites and common areas.

### SOLUTION

The RSC-900 system with wireless sensors was installed through the suites, automatic water shut-off valve/actuators, and wireless water meter readers.

By monitoring the water meter(s) in each suite, staff can be alerted of high water use in real time and if there are broken water pipes. Sensors and water flow monitoring protect the suites.

